Taylor, Kevin [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP From: (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=C9483DA991924F4D9BC80D5624B14799-TAYLOR, KEVIN] Sent: 9/9/2021 12:38:52 PM To: Pruitt, Landon [Pruitt.Landon@epa.gov]; Kler, Denis [Kler.Denis@epa.gov]; Mills, Andrew [mills.andrew@epa.gov]; Dressler, Jason [Dressler.Jason@epa.gov]; Pratt, Marirose [Pratt.Marirose@epa.gov]; Fried, Gregory [Fried.Gregory@epa.gov]; Caballero, Kathryn [Caballero.Kathryn@epa.gov]; Foley, Patrick [Foley.Patrick@epa.gov]; Secrest, Cary [Secrest.Cary@epa.gov]; Russo, Todd [Russo.Todd@epa.gov]; Aker, Sandra [Aker.Sandra@epa.gov]; Wellborn, Floyd [Wellborn.Floyd@epa.gov]; Zachary, Adam [zachary.adam@epa.gov]; Guillot, Richard [Guillot.Richard@epa.gov]; Montalvo, Liza [Montalvo.Liza@epa.gov] BCC: Kevin Taylor [Taylor.Kevin@epa.gov] Subject: Update: New Indy Follow Up to EPA Fence Line Monitoring QAPP Review Attachments: ATT00001.txt; AM-150_API_T101SOP_rev01_08-27-21.pdf; On-Site_NewIndyMonthlyReport_27May2021 to 26Jun2021 (08-10-21).pdf; TRC Offset Calculations - NICB Onsite Monitors.docx; On-Site NewIndyMonthlyReport 27Jun2021 to 31Jul2021 (09-03-21).pdf This is all of the attachments that were sent by New Indy yesterday and the July monthly report that was sent this morning. Sincerely, Kevin I. Taylor Environmental Engineer|Air Enforcement Branch (AEB) Enforcement And Compliance Assurance Division (ECAD) U.S. Environmental Protection Agency | Region 4 61 Forsyth Street, S.W. Atlanta, GA 30303 (404) 562-9134|taylor.kevin@epa.gov ----Original Message----From: Pruitt, Landon <Pruitt.Landon@epa.gov> Sent: Thursday, September 9, 2021 8:27 AM To: Taylor, Kevin <Taylor.Kevin@epa.gov> Cc: Kler, Denis <Kler.Denis@epa.gov>; Mills, Andrew <mills.andrew@epa.gov>; Dressler, Jason <Dressler.Jason@epa.gov>; Pratt, Marirose <Pratt.Marirose@epa.gov>; Fried, Gregory
<Fried.Gregory@epa.gov>; Caballero, Kathryn <Caballero.Kathryn@epa.gov>; Foley, Patrick <Foley.Patrick@epa.gov>; Secrest, Cary <Secrest.Cary@epa.gov>; Russo, Todd <Russo.Todd@epa.gov>; Aker,
Sandra <Aker.Sandra@epa.gov>; Wellborn, Floyd <Wellborn.Floyd@epa.gov>; Zachary, Adam <zachary.adam@epa.gov>; Guillot, Richard <Guillot.Richard@epa.gov>; Montalvo, Liza <Montalvo.Liza@epa.gov> Subject: Re: New Indy Follow Up to EPA Fence Line Monitoring QAPP Review I don't see anything beyond Adam and Richard's comments. -Landon > On Sep 8, 2021, at 2:14 PM, Taylor, Kevin <Taylor.Kevin@epa.gov> wrote: > Sincerely, Kevin I. Taylor > Environmental Engineer|Air Enforcement Branch (AEB) Enforcement And Compliance Assurance Division (ECAD) U.S. Environmental Protection Agency | Region 4 > 61 Forsyth Street, S.W. | Atlanta, GA 30303 (404) 562-9134|taylor.kevin@epa.gov > From: Dan Mallett <Dan.Mallett@new-indycb.com> > Sent: Wednesday, September 8, 2021 1:32 PM To: Taylor, Kevin <Taylor.Kevin@epa.gov>; Pete Cleveland <pete.cleveland@new-indycb.com> > Cc: Russo, Todd <Russo.Todd@epa.gov> > Subject: New Indy Follow Up to EPA Fence Line Monitoring QAPP Review > Importance: High Good afternoon Kevin and Todd, Attached please find the following documents as requested during our September 2, 2021 online meeting: TRC Offset Calculations for #1 Monitoring Station 2. QAPP SOP

```
> for Daily QA data management
          If the daily automated precision check is <7% - it passes.
          If the check is 7\% - 10\% - Alert. Do a manual precision check to verify results. Can
recalibrate, without adjustment, as a precaution. No data invalidated.

* If the check is > 10% - Action required. Conduct a multipoint calibration or manual precision
check. If multipoint verification is <10% for all points no additional action needed. If check >10%, then
it fails and we have to recalibrate. Then invalidate data to previous passing QC check.
  June 2021 Monthly Report
> According to our consultant, TRC Environmental, the July report is undergoing final peer review.
                                                                                                       New-
Indy shall forward the completed document to the USEPA Region 4 as soon as it is received from our
consultant.
> Please call if you should require more information.
> Regards.
> DANIEL MALLETT
> Environmental Manager
> Office:
            (803) 981-8010
> Mobile: (207) 951-6216
> [cid:image001.jpg@01D7A4B4.A5AB3B50]
> From: Taylor, Kevin
> <Taylor.Kevin@epa.gov<mailto:Taylor.Kevin@epa.gov>>
> Sent: Wednesday, September 8, 2021 10:38 AM
> To: Dan Mallett
> <Dan.Mallett@new-indycb.com<mailto:Dan.Mallett@new-indycb.com>>; Pete
> Cleveland
> <pete.cleveland@new-indycb.com<mailto:pete.cleveland@new-indycb.com>>
> Cc: Russo, Todd <Russo.Todd@epa.gov<mailto:Russo.Todd@epa.gov>>
> Subject: RE: New Indy Follow Up to EPA Fence Line Monitoring QAPP
> External E-Mail - Caution - This email originated outside of New-Indy. .
> Hi Dan.
> In checking with LSASD on the information requested, I received the following response:
> Per the information request during the September 2nd meeting, the monthly reports (i.e., June and July
2021) from Section 3.2.2 of the New Indy QAPP were requested. These reports should include the
interpretation procedure for data management after a failed quality control check. Also, the correction
factor calculations for meteorological sensors at stations 1 and 3 were requested.
> I hope this is helpful. Please let me know if you have any additional questions or comments and please
provide an estimate on when this information will be available.
> Thank you.
> Kevin
> Sincerely,
 Kevin I. Taylor
> Environmental Engineer | Air Enforcement Branch (AEB) Enforcement And
> Compliance Assurance Division (ECAD) U.S. Environmental Protection
  Agency | Region 4
> 61 Forsyth Street, S.W. | Atlanta, GA 30303
> (404)
> 562-9134|taylor.kevin@epa.gov<mailto:562-9134|taylor.kevin@epa.gov>
> From: Dan Mallett
> <Dan.Mallett@new-indycb.com<mailto:Dan.Mallett@new-indycb.com>>
> Sent: Tuesday, September 7, 2021 1:02 PM
> To: Taylor, Kevin <Taylor.Kevin@epa.gov<mailto:Taylor.Kevin@epa.gov>>;
> Pete Cleveland
> <pete.cleveland@new-indycb.com<mailto:pete.cleveland@new-indycb.com>>
> Cc: Russo, Todd <Russo.Todd@epa.gov<mailto:Russo.Todd@epa.gov>>
> Subject: RE: New Indy Follow Up to EPA Fence Line Monitoring QAPP
> Review
> Good day Kevin,
> My apologies for this oversight. I have reached out to TRC to determine the status of this request.
My notes state the following information is due:
      Interpretation procedure for data management after a failed QA.
   2.
       Correction factor calcs for the offset at #1 monitor.
```

```
> Please advise if I am incorrect and I will provide an update on the status of this information.
 Regards.
>
> DANIEL MALLETT
  Environmental Manager
> Office:
            (803) 981-8010
> Mobile: (207) 951-6216
  [cid:image001.jpg@01D7A3E8.8E6828D0]
 From: Taylor, Kevin
 <Taylor.Kevin@epa.gov<mailto:Taylor.Kevin@epa.gov>>
> Sent: Tuesday, September 7, 2021 11:32 AM
> To: Pete Cleveland
> <pete.cleveland@new-indycb.com<mailto:pete.cleveland@new-indycb.com>>;
> Dan Mallett
> <Dan.Mallett@new-indycb.com<mailto:Dan.Mallett@new-indycb.com>>
  Cc: Russo, Todd <Russo.Todd@epa.gov<mailto:Russo.Todd@epa.gov>>
> Subject: New Indy Follow Up to EPA Fence Line Monitoring QAPP Review
> External E-Mail - Caution - This email originated outside of New-Indy. .
> Pete/Dan.
> On the call last Thursday, September 2, 2021, the EPA Laboratory Services and Applied Science Division
(LSASD) requested some additional information to complete their review of the QAPP for the fence line
monitors. Please let us know when we should expect the follow up information requested. If a listing of
the information discussed is needed, please let me know and I will provide it to you.
> Thank you.
  Kevin
>
> Sincerely,
> Kevin I. Taylor
> Environmental Engineer|Air Enforcement Branch (AEB) Enforcement And
> Compliance Assurance Division (ECAD) U.S. Environmental Protection
  Agency | Region 4
> 61 Forsyth Street, S.W. Atlanta, GA 30303
  (404)
> 562-9134|taylor.kevin@epa.gov<mailto:562-9134|taylor.kevin@epa.gov>
> NOTICE: This message and any attachments are solely for the intended recipient and may contain confidential or privileged information. If you are not the intended recipient, you are hereby notified
that any review, dissemination, distribution or duplication of this message and any attachments is
prohibited. If you have received this communication in error, please notify us by reply email and immediately and permanently delete this message and any attachments. Email transmission may not be secure
and could contain errors. We accept no liability for any damage caused by any virus transmitted by this
email. Please do not send to us by email any information containing personally identifiable information
without appropriate encryption. Thank you.
> The content image001.jpg of type has been blocked.
> <On-Site_NewIndyMonthlyReport_27May2021 to 26Jun2021 (08-10-21).pdf>
```